

SANITARY	ADDRESS: <u>2560 ABBEYGLEN WAY</u> LOT: <u>7</u> BLK: <u> </u> RP: <u>72965</u>	WATER
----------	---	-------

S- <u>2.69-W-SE</u> INV. <u>874.586</u> R <u> </u> Y- <u> </u> SIZE <u>100</u> TYPE <u>PVC</u> INSTALLED <u>2002</u> CONNECTED <u> </u> ELEV. <u> </u>	STORM ST- <u>3.01-W-SE</u> INV. <u>874.542</u> R <u> </u> Y- <u> </u> SIZE <u>100</u> TYPE <u>PVC</u> INSTALLED <u>2002</u> CONNECTED <u> </u>	W- <u>3.43-W-SE</u> <u> </u> OUT FROM APPROX. DEPTH <u>1.80m</u> SIZE <u>19</u> TYPE <u>Kitec</u> INSTALLED <u>2002</u> CONNECTED <u> </u>
--	---	---

10-02-2003

SANITARY	ADDRESS: <u>2554 ABBEYGLEN WAY</u> LOT: <u>8</u> BLK: <u> </u> RP: <u>72965</u>	WATER
----------	---	-------

S- <u>2.97-W-SE</u> INV. <u>873.502</u> R <u> </u> Y- <u> </u> SIZE <u>100</u> TYPE <u>PVC</u> INSTALLED <u>2002</u> CONNECTED <u> </u> ELEV. <u> </u>	STORM ST- <u>3.40-W-SE</u> INV. <u>873.520</u> R <u> </u> Y- <u> </u> SIZE <u>100</u> TYPE <u>PVC</u> INSTALLED <u>2002</u> CONNECTED <u> </u>	W- <u>3.45-W-SE</u> <u> </u> OUT FROM APPROX. DEPTH <u>1.80m</u> SIZE <u>19</u> TYPE <u>Kitec</u> INSTALLED <u>2002</u> CONNECTED <u> </u>
--	---	---

10-02-2003

SANITARY	ADDRESS: <u>2542 ABBEYGLEN WAY</u> LOT: <u>10</u> BLK: <u> </u> RP: <u>72965</u>	WATER
----------	--	-------

S- <u>4.40-W-SE</u> INV. <u>871.103</u> R <u> </u> Y- <u> </u> SIZE <u>100</u> TYPE <u>PVC</u> INSTALLED <u>2002</u> CONNECTED <u> </u> ELEV. <u> </u>	STORM ST- <u>4.75-W-SE</u> INV. <u>871.065</u> R <u> </u> Y- <u> </u> SIZE <u>100</u> TYPE <u>PVC</u> INSTALLED <u>2002</u> CONNECTED <u> </u>	W- <u>5.20-W-SE</u> <u> </u> OUT FROM APPROX. DEPTH <u>1.80m</u> SIZE <u>19</u> TYPE <u>Kitec</u> INSTALLED <u>2002</u> CONNECTED <u> </u>
--	---	---

10-02-2003